Spartan Wood Floor Care Notes & Trouble Shooting

IMPORTANT NOTES:

- 1. Be sure the floor is properly prepared.
- 2. Do not coat with conventional floor finish.
- 3. Use duct tape to "de-fuzz" all applicators before using.
- 4. Thoroughly clean area to ensure a dust free environment.
- 5. Follow recommended grit # for screening.
- 6. Always use screens; do not use stripping pads.
- 7. Be sure to adequately and properly tack until no residue is left on the floor. Be certain the floor is thoroughly clean. Do not reuse towels or tack rags.
- 8. Do not use oil treated dust mops for sweeping and tacking.
- 9. Do not use soap-based detergents.
- 10. Do not use old material.
- 11. Do not create puddles or heavy lap ridgelines. Should they occur, work out immediately.
- 12. Maintain a "wet" edge during the finish application.
- 13. Do not shake finish before applying or over work the product during application.
- 14. Do not apply product too thick. Apply at recommended square foot coverage.
- 15. Allow floor to thoroughly dry before coating.
- 16. Do not close up the area where the floor is being coated good gentle ventilation is required for proper cure.
- 17. Do not use fans directly on drying finish.
- 1. Do not use tape as court lines.
- 18. Use A-Tack to clean up solvent-based equipment. Use water to clean up water-based equipment.
- 19. Do not apply solvent-based seal or finish over a water-based seal or finish.
- 20. Following drying and curing recommendations between coats and prior to traffic.
- 21. <u>Dry times vary depending on temperature and humidity at the time of application.</u>
 The product will cure slower at lower temperatures, faster at higher temperatures and much slower at higher humidity. Avoid application on or preceding extremely hot and/or humid days.
- 22. <u>Do not apply when temperatures are below 65°F or above 90°F. Do not apply when relative humidity is 80% or greater.</u>

TROUBLE SHOOTING:

Slow Dry:

- Low-curing temperatures.
- High humidity.
- Lack of ventilation and need for gentle air movement after application.
- Too thick, not working out puddles and lap lines.
- Too much air movement.
- Applying seal/finish before tack rag compound has completely evaporated.

Streaks:

- Product applied too thin.

Fisheyes:

- A foreign material on surface, like oil, grease, or silicone.
- Poor (rushed) tack job.

Bubbling:

- Overworking the product with applicator.
- High temperatures during application.

Wrinkling:

- Re-coating too soon.
- Heavy finish application.
- High temperatures during application.

Peeling:

- Improper preparation.
- Failure to re-screen after 24 hours.
- In cases of solvent-based seal or finish, application over a waterbased seal or finish can result in peeling.